

Fail 2016		Plot	
FAIL		I	15
FAIL		II	8 & 9
FAIL		IV	5 & 6
FAIL		IX	32
FAIL		IX	6 & 7
FAIL	need digger	LIII	21
FAIL		LXIX	6
FAIL		LXVI	32
FAIL		LXXVI	23
FAIL		V	50
FAIL		V	28 & 29
FAIL		VI	3
FAIL		VI	4

FAIL	over	VI	14 & 15
FAIL		VIII	30
FAIL		VIII	16 & 17
FAIL		X	22
FAIL		X	13 & 14
FAIL		X	18 & 19
FAIL		XXI	13
	Slight movement	II	34
	cross down	LXIX	13
	down	LXX	37
	down	LXX	39
	down	LXX	18
	down	LXXII	2
	down	LXXII	5
	down	LXXII	8

	down	LXXII	20
	down	LXXII	33
	down	LXXIV	12
	down	LXXIV	33
	old down	LXXVII	10
	down	V	22
	KERB TIED ALREADY	XXXVI	35

--	--	--	--

Update Oct 2017

Fail 2016		Plot		Repaired
FAIL		I	15	
FAIL		II	8 & 9	
FAIL		IV	5 & 6	
		IX	32	YES
FAIL		IX	6 & 7	
FAIL	need digger	LIII	21	
FAIL		LXIX	6	
FAIL		LXVI	32	
FAIL		LXXVI	23	YES
FAIL		V	50	YES
FAIL		V	28 & 29	
FAIL		V	3	YES
FAIL		V	4	YES
FAIL	Laid down	VI	14 & 15	
FAIL		VIII	30	
FAIL		VIII	16 & 17	
FAIL		X	22	YES
FAIL		X	13 & 14	
FAIL		X	18 & 19	
FAIL		XXI	13	
FAIL		LXXIV		YES

CHECK	See XXXXXX notes for Shirley Ann	XVIII	3	
--------------	----------------------------------	-------	---	--

MEMORIAL INSPECTION - 2017

Inspection No	Grave Space	Plot No	Precautions taken/planned
1	LIII	21	Large Memorial deemed dangerous and unsafe. Digger hired for 31 October to turn around and lay flat by CTC. This is a previous fail.
2	LXVI	32	Laid down 26.10.17
3 (no photo)	X	13 & 14	16" high. Left as is. 25.10.17
4	X	18 & 19	Re-staked, banded and made safe by CTC 26.10.17
5	VIII	16 & 17	Repaired by stonemasons
6	II	8 & 9	Re-staked, banded and made safe by CTC 25.10.17
7	IV	5 & 6	Re-staked, banded and made safe by CTC 25.10.17
8	I	15	Re-staked, banded and made safe by CTC 25.10.17
9	V	28 & 29	Made safe and repaired by stonemasons
10	VIII	30	Re-staked, banded and made safe by CTC 25.10.17
11	LXXIV	1A	Re-staked, banded and made safe by CTC 26.10.17